



Turtle Beach Ear Force Stealth 500P Headband Pad Replacement

A guide for replacing the headband pad on Turtle Beach Ear Force Stealth 500P headphones.

Written By: Noah Franklin



INTRODUCTION

In order to complete this repair, you will need to order a replacement headband to replace the defective part.



TOOLS:


- [Metal Spudger](#) (1)
-

Step 1 — Headband Pad



- Grab one end of the headband pad and pull up slightly, exposing where it is glued to the backing.

Step 2



- Using a thin tool carefully scrape away the glue underneath the band while pulling the pad up, careful not to rip it.

Step 3



- Once the pad has been completely removed, scrape off any remaining residue.

Step 4



- Follow the directions of the replacement pad on how to attach it to the headband.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-11-24 08:04:56 PM.